



Pakistan Oilfields Limited HSE Bulletin



March, 2022

"KEEP SAFETY AT THE FIRST STEP"

HYDROGEN SULFIDE (H2S)

What is Hydrogen Sulfide (H₂S)?

H2S is poisonous, corrosive and flammable gas having a characteristic foul odor of rotten eggs. Hydrogen sulfide is a colorless, flammable, toxic gas. It is also called silent killer as it paralyze the olfactory nerves (sense of smell). It is formed due to degradation of organic matters. It is commonly found during the drilling and production of crude oil and natural gas. It also occurs in sewers.

H₂S PROPERTIES & CHARACTERISTICS

Following are the properties of hydrogen sulphide:-

- H₂S is heavier than air and tends to settle down in low-lying areas. It is rarely dispersed by wind movement due to its heavier nature.
- It is extremely corrosive to certain metals and may weaken the metallic structures and containers.



 High concentration of H₂S can affects the ability to smell. Thus smell is not a reliable mean of detecting H₂S.



- It is slightly soluble in water and release when the mixture is agitated.
- It burns with blue flame and produce other toxic vapors and gases, such as sulfur dioxide.



 Forms a flammable and explosive environment
between 4.3% and 46% in

between 4.3% and 46% in relativity of air.

How dangerous is H₂S?

Hydrogen sulfide is extremely toxic gas and can cause possible life-threatening situations if not properly handled. Exposure to very high concentrations can quickly lead to death.

The exposure limits for H₂S as set by OSHA are:

- Thresh hold limit value (TLV) is 10 ppm for 8 hours without PPEs'.
- Short time exposure limit (STEL) is 15 ppm for 15 minutes without PPEs'.
- Evacuate at 20 ppm and do not work without breathing aid.
- Immediate Dangerous to Life and Health (IDLH) is 100 ppm.

Where to Expect H₂S Exposure?

Some of the activities/areas where H₂S exposure is very likely are;

- Drilling operations through production zones.
- Well testing and work over activities.
- Near well heads, process vessels and plant areas.
- Near manholes of sewage lines.

How H₂S is detected?

There are reliable means available to detect and alert from H_2S presence. One should never rely on his nose as it kills sense of smell. Following means of detection can be used for H_2S detection.

Fixed H₂S detectors

Fixed detectors are typically used in plant areas and drilling operations for continuous monitoring where chances of H₂S presence are higher. These detectors are coupled with a



control panel installed in safe area to remotely monitor the H_2S levels. If H_2S levels increase above certain limits, an alarm will be activated.

Portable H₂S detectors

Portable detectors are typically used for spot checking when working in areas where H₂S exposure is likely to occur. These detectors are battery operated and triggers alarm



when H₂S concentrations are above TLV limits.

Personal H2S detectors

Personal detecotrs are used staff while routine working in plants where probability of H₂S occurenece is graeter. These detectors triggers alarm when H₂S concentrations are above TLV limits.



How to Avoid H₂S Exposure?

Avoiding exposure to hydrogen sulfide is the best way of protection. Following are some ways to avoid H2S exposure:-

- H2S scavengers can be added to remove hydrogen sulfide from liquid and gas streams at plants.
- Proper & timely maintenance of H₂S handling plant, equipments, vessels, pipelines to avoid H₂S leakages.
- H₂S monitoring through fixed and portable detectors be carried out to detect H₂S presence.
 - Air quality must be checked before entering confined spaces i.e. Process vessels, tanks, cellars and sewerage system drains / tanks.
- Use of ventilation systems before entry into confined spaces, process vessels, tanks, cellars and sewerage systems.
- Use of appropriate PPEs (SCBA, Fresh air mask, BA trolleys H₂S etc.) environment





First Aid for H₂S Exposure

For workers who overcome by hydrogen sulfide, following are measures to be taken:-

- a) Rescuers must wear appropriate PPE's
- b) Immediately remove the victim from further exposure and move to a safe location.
- c) If the victim is not breathing, apply cardiopulmonary resuscitation (CPR).



01 CHECK FOR RESPONSE







02 ESTABLISH AN AIRWAY

03 CHECK FOR BREATHING

d) If the victim eyes are red and painful, flush with large amounts of clean water.

ہائیڈروجن سلفائیڈ ایک جمڑ نے والی گیس ہے جو نیلے رنگ کا شعلہ پیدا کرتی ہے ۔سلفرآ کسائیڈ کا بڑھنا ایک تیز چینے والی بوکر پیدا کرے گا۔ ہائیڈروجن سلفائیڈ اور ہوا کا لماپ ایک دھماکے کا سبب بن سکتا ہے۔ چونکداس کے ذرات ہواہے بھاری ہوتے ہیں،اس لئے اس کیس کے ذرات زمین کے ویر ہی رہتے ہیں۔

. اگراسگیس کاافراج انتہائی معمولی ہو، تب بھی یہ متاثر ہونے والے شخص کے سرور د، نیم بے ہوشی اور آنکھوں کے نقصان کا بھی سب بن سکتی ہے جبکہ زیادہ مقدار کا اخراج فوری موت کا باعث بھی بن سکتا ہے ہیپورت کے نالوں اور گٹر وغیر و میں اس گیس کی موجود گی، زیادہ اموات کی ہویہ بن



• آیریشن کے دوران ہائع اور گیس ہے ائیڈروجن سلفائیڈ کو فکالنے کے لیے II2S اسکیو ینجرز کو شامل کیا حاسکتا ہے۔ •H2S بیٹا لنگ بلان، سازوسلان، پائی لا ننول کی مناب اور بروقت دیکے بھال تاکہ H2S کے رساوے بحاجا سکے۔ •H2S کی موجود گاکا بیتہ لگانے کے لیے فکسڈ اور اور ٹیمل ڈیمکٹر کے ذریعے H2S کی تحریاتی جادوں چیزی روسین ٹیمکوں، تہر حانوں اور سپور تن سٹم کے نالوں / ٹینکوں میں داخل ہونے ہے بہلے ہوائے معیار کی جانج ہونی جاہے۔ • محدود جگوں، پروسین فیکوں، تھانے اورسیور تا سٹم می داخل ہونے سے پہلے دینٹملیش سٹم کاستمال •H2S احول مين مناسبPPEs (SCBA، فريش ايرُ مامك، BAڑ اليان وغير و) كاستعال

• آیریشن کے دوران ہائع اور گیس ہے ائیڈروجن سلفائیڈ کو فکالنے کے لیے H2S اسکیو پنجر زکوشال کما حاسکا ہے۔ •H2S بنڈ لنگ بانٹ مازوملان، پائسالا مُول کی منامب اور بروقت دیکھ بجال تاکہ H2S کے رساوے بحاجا سکے۔ •H2S کی موجود گایا بیۃ لگانے کے لیے فکسڈاور پورٹیل ڈیمکٹر کے ذریع H2S کی تحرانی کی جائے۔ محدود جگیوں لیخی پروسیس ٹیمکوں، تہر خانوں اور سیور تئ سٹم کے نالوں / ٹینکوں میں داخل ہونے بہلے ہواکے معار کی جانچ ہونی جاہے۔ مود جگہوں، پروسیں مُنکوں، تھانے اور سیور یک سٹم میں داخل ہونے ہے پہلے وینٹیلیش سٹم کا استعال •H2S مناب PPEs (SCBA فریش ایئر مایک BA ٹرالیاں وغیر و) کااستعال



H2S کے لیے ابتدائی طبی امداد

ہائیڈروجن سلفائیڈیر قابویانے والے کار کنوں کے لیے، درج ذیل اقدامات کیے جائیں: -

- ريسكورز كومناسب PPE يېنناچا ہے۔
- متاثره کو فوری طور پر مزید نقصان بے بٹائیں اور محفوظ مقام پر منتقل کریں۔
- اگرمتاژه څخص سانس نہیں لے رہاہے تو کارڈیو پلونری ریسیسیٹیشن (CPR) لگائی۔

